



















LUXOR 1146 -1 Montážny návod

Ax1 	Bx1 
Cx2 	Dx1 
Ex2 	Fx2  (14.5cm)
Gx2 	Hx4 
I x6 	Jx1 
Kx6 (5*50) 	Lx22 (8*20) 
Mx10 (8*50) 	Nx32 
Ox32 	Px16 
Qx1 	Rx2  (3.5*30)

