











Ø8





A0 8 x 32mm 	C0 	C2 
C7 16mm 	D0 3 x 15 mm 	D16 4,2 x 28 mm 
D21 5 x 13 mm 	E0 5 x 70 mm 8 x 50 mm 	M1 
P0 	Q3 	T3 








1	1152	320	16	x1	1/1
2	1152	320	16	x1	1/1
3	568	320	16	x1	1/1
4	568	320	16	x1	1/1
5	568	298	16	x2	1/1
6	1130	578	3	x1	1/1
					1/1








1 ►



2▶





A0 8 x 32mm x8 	C7 16mm x8 
---	---













5▶



D0	3 x 15 mm	x10	M1	x10
				







6 ▶








7 ▶

D21 5 x 13 mm 	x1	E0 5 x 70 mm 8 x 50 mm 	x1	P0 	x1
--	-----------	--	-----------	--	-----------



8 ▶



9 ▶

