




























REGIA TYP 10



NO	Dim.		Col.-No	Qty
1	280	306	1	4
2	970	284	1	4
4	244	246	1	4
5	982	258	1	2
6	884	274	1	2
7	246	60	1	4

REGIA TYP 10




REGIA TYP 10

1

A1

x16





B5

x16



G7

x16



2




A1

x16





B4

x16




x4



x4


REGIA TYP 10

3




E21	Ø35 H=0	D10
x4		x8

USØ3,5x13




x2


6




4




x2



5




6




REGIA TYP 10




7





8




9




x2






10 - 11





12 - 13







10





11





12






13



REGIA TYP 30



(30)





120 min

NO	Dim.		Col.-No	Qty
1	1752	370	1	1
2	1752	370	1	1
3	226	348	1	1
4	226	348	1	1
5	226	328	1	1
6	226	328	1	1
7	582	180	1	2
8	578	318	1	1
9	568	238	1	2
10	592	238	1	1
11	554	60	1	2

REGIA TYP 30




A1 x24		B4 x8		B5 x8		G5 x8		B11 x8		L1 x2	
E25 x4		E4 x4		D10 x18		G21 x2		D7 x6		G7 x4	
I11 x6		UP15 x6		S1 x14		G16 x2		UP13 x2			



1

A1	
X8	ø8x36

B5	
X4	Ø15x12



REGIA TYP 30

2

A1

x8

B5


x4

G7

x4





Ø15x12



3



A1	
x8	ø8x36





x2

4







I11	
x6	Ø50, h=25
UP15	
x6	UPØ4x25
E4	
x4	H=2



5





6






7

x2

7





8



9




G5	
x8	




10

 $X=Y \uparrow 90^\circ$ 



S1 x14	G16 x2	UP13 x2	UP03x16
-----------	-----------	------------	---------




11



L1 x2		D10 x4	
			USØ3,5x13



12



13

G21

x2

D7

x6

USØ3x16

D10

x6

USØ3,5x13

