








Ø8



A









B






MM
260
250

A0 8 x 30mm 	x12	C0 	x12	C2 	x16
C7 16mm 	x16	D0 3 x 15 mm 	x21	D4 3,5 x 18 mm 	x6
D10 4 x 16 mm 	x12	D12 4 x 25 mm 	x20	E0 5 x 50 mm 8 x 50 mm 	x1
J6 	x6	J8 	x6	M1 	x14
M3 	x5	P0 	x1	Q0 	x8
Q1 	x8	T5 	x5	U1 	x6
U6 	x6				



240
230
220
210
200
190
180
170
160
150
140
130
120
110
100
90
80
70
60
50
40
30
20
10
0








1	1330	350	16	x1	1/2
2	1330	330	16	x1	1/2
3	901	370	16	x1	1/2
4	901	370	16	x1	1/2
5	1324	230	16	x1	2/2
6	1324	90	16	x1	2/2
7	1330	350	16	x1	1/2

8	324	298	16	x2	1/2
9	1324	296	16	x1	2/2
10	1340	536	3	x1	1/2
11	1340	337	3	x1	1/2
12	1330	72	32	x1	1/2
13	524	295	5	x2	2/2
14	1324	310	4	x1	2/2
					1/2








1 ▶




2 ▶




3▶

(A0) 8 x 30mm 	(C2) 	(C7) 16mm 
x4	x4	x4




4▶

(C2) 	x6
--	-----------




5▶

(C2) 	x6
--	-----------




6▶


(C7) 16mm 	x4
--	-----------




7 ▶




8 ▶ A




8 ► B





9 ► A








9 ► B




10 ►




D0 3 x 15 mm 	x19	M1 	x14	M3 	x5
---	------------	--	------------	--	-----------




12 ► A







12 ► B




13




D10	4 x 16 mm	x6	J8	x3
				




D4	3,5 x 18 mm	x6	D10	4 x 16 mm	x6	J8	x3
							
U1		x6	U6		x6		
							









14







15 ► A












15 ► B
















16 ▶ A

(D0) 3 x 15 mm  x2	(E0) 5 x 50 mm 8 x 50 mm  x1	(P0)  x1
(Q0)  x8	(Q1)  x8	




16 ► B


D0 3 x 15 mm 	E0 5 x 50 mm 8 x 50 mm 	P0 
Q0 	Q1 	



17▶A



17 ► B



18 ►

