





Ø8










A




B





A0 8 x 32mm  x8	C0  x4	C2  x8
C7 16mm  x8	D0 3 x 15 mm  x10	D10 4 x 16 mm  x12
D16 4,2 x 28 mm  x8	D21 5 x 13 mm  x1	E0 5 x 70 mm 8 x 50 mm  x1
J6 D30  x6	J8  x6	L0  x2
M1  x10	P0  x1	Q3  x8
T3  x4	U0  x4	




A





B



1	1152	320	16	x1	1/1
2	1152	320	16	x1	1/1
3	568	320	16	x1	1/1
4	568	320	16	x1	1/1
5	1149	297	16	x1	1/1
6	1149	297	16	x1	1/1
7	568	298	16	x2	1/1
8	1130	578	3	x1	1/1
					1/1






1 ►



2▶





A0	8 x 32mm	x8	C7		x8
			16mm		










5▶


D0	3 x 15 mm	x10	M1	x10
				







6 ▶








7 ▶


D21 5 x 13 mm  x1	E0 5 x 70 mm  8 x 50 mm  x1	P0  x1
--	---	--




8 ▶






D10 4 x 16 mm x12 	J8  x6	U0  x4
--	--	--










10A▶

D16 4,2 x 28 mm x4 	L0 x2 
---	---





10B ►



D16	4,2 x 28 mm	x4	L0	x2
				



11A▶



11B ►



12▶

